

09911754

Call
BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

TELEPHONE (408) 720-8300

FACSIMILE (408) 720-8383

bstz.mail@bstz.com

www.bstz.com

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

SILICON VALLEY/SAN JOSE, CA
LOS ANGELES, CA

ORANGE COUNTY/COSTA MESA, CA
PORTLAND/LAKE OSWEGO, OR
SEATTLE, WA
DENVER, CO
AUSTIN, TX

January 28, 2004

*Certificate
FEB 09 2004
of Correction*

Commissioner For Patents
PO BOX 1450
Alexandria, VA 22313-1450

Re: **CERTIFICATE OF CORRECTION**
U. S. Letters Patent No. 6,674,648
Issued: Jan. 6, 2004
For: **TERMINATION CARDS AND SYSTEMS**
THEREFORE
Inventor: McCall et al.
Our File No. 42390.P11993

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Ed Taylor
Edwin H. Taylor
Reg. No. 25,129

EHT/gx
Enclosures

FEB 10 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,674,648

DATED : Jan. 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6, line 35, delete "12,14,15, and 17", insert -- I2, I4, I5, and I7--.

In column 10, line 44, delete "12", insert -I2--.

In column 10, line 67, delete "P60", insert -P62--.

In column 13, from line 57 to line 59, delete "chips 18 and 116 of module 1 and chips 18 and 116 of module 2. The on die terminations are enabled in chips 17 and 115 of module 1 and 17 and 115", insert - chips I8 and I16 of module 1 and chips I8 and I16 of module 2. The on die terminations are enabled in chips I7 and I15 of module 1 and I7 and I15 --.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,674,648

Certificate of Correction (PTO Form 1050)-Amended

FEB 10 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,674,648

DATED : Jan. 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6, line 35, delete "12,14,15, and 17", insert -- I2, I4, I5, and I7--.

In column 10, line 44, delete "12", insert -I2--.

In column 10, line 67, delete "P60", insert -P62--.

In column 13, from line 57 to line 59, delete "chips 18 and 116 of module 1 and chips 18 and 116 of module 2. The on die terminations are enabled in chips 17 and 115 of module 1 and 17 and 115", insert - chips I8 and I16 of module 1 and chips I8 and I16 of module 2. The on die terminations are enabled in chips I7 and I15 of module 1 and I7 and I15 --.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,674,648

Certificate of Correction (PTO Form 1050)-Amended

FEB 10 2004